

# REDACTED

From: Justin Quach/NA/BASF

To: John Bodmann/BASF-CATALYSTS/BASF@BASF, William Grodecki/NA/BASF@BASF, Kristen Kaput/NA/BASF@BASF

Cc: Leon Zavodnik/BASF-CATALYSTS/BASF@BASF, Noemi Trent/BASF-CATALYSTS/BASF@BASF, Robert Scoggins/NA/BASF@BASF, Terrence M Vanderbosch/BASF-CATALYSTS/BASF@BASF, Stefan J Niewiadomski/BASF-CATALYSTS/BASF@BASF

Date: 10/28/2014 05:06 PM

Subject: Building 9 PK Blender Batch Sheets

---

All,

The building 9 dust collector is now running at a higher RPM, has half of the bags inside, and is running around 3.6" H2O.

This is with one of the unused ports open on the main ductwork to help pull in extra air. I know we've already had a safety meeting presentation about it, but **please make sure if you have any product running on the PK that your batch sheet reflects the importance of checking the gauges before making a batch.**

For instance, here is my batch sheet for AI-3915 pillmix. There is a note at the top about checking the dust collector gauges before making each batch, as well as a field below to fill in the differential pressure for each batch. This should help to ensure they are checking this on a batch by batch basis. Thanks



Regards,

---

**Justin Quach**

Process Engineer - Catalysts

Phone: 440-329-2501, Mobile: 440-822-9800, Fax: 440-329-2403, E-Mail: [Justin.Quach@basf.com](mailto:Justin.Quach@basf.com)

Postal Address: Catalysts Division, BASF Corporation, 120 Pine St, Elyria, OH 44035

BASF Corporation - The Chemical Company